

CC2674P10 SimpleLink™ Wireless MCU Device Revision C



Table of Contents

1	Advisories Matrix	2
2	Nomenclature, Package Symbolization, and Revision Identification	3
2.1	Device and Development Support-Tool Nomenclature	3
2.2	Devices Supported	3
2.3	Package Symbolization and Revision Identification	3
3	Advisories	4
4	Revision History	10

Trademarks

Texas Instruments™ is a trademark of Texas Instruments.
All trademarks are the property of their respective owners.

1 Advisories Matrix

Table 1-1 lists all carried over and new advisories and modules affected for silicon revision C from the previous revision. Advisories that have been addressed in revision C are removed from the list. Please see the revision history for a complete list of advisories that are removed and no longer present in this errata and new advisories added.

Table 1-1. Advisories Matrix

MODULE	DESCRIPTION	SILICON REVISIONS AFFECTED
		C
Radio	Advisory Radio_01 — Proprietary radio modes: spurious emissions can affect regulatory compliance	Yes
Radio	Advisory Radio_02 — High-power PA operation at temperatures below -20°C may affect the 32kHz crystal oscillator.	Yes
Radio	Advisory Radio_05 — Zigbee has a negative 3dB RSSI offset error with internal bias	Yes
Power	Advisory Power_03 — Increased voltage ripple at low supply voltages when DC/DC converter is enabled.	Yes
PKA	Advisory PKA_01 — Public key accelerator (PKA) interrupt line is always high when module is enabled and PKA is idle.	Yes
PKA	Advisory PKA_02 — Public key accelerator (PKA) RAM is not byte accessible.	Yes
I2C	Advisory I2C_01 — I ² C module master status bit is set late.	Yes
I2S	Advisory I2S_01 — I ² S bus faults are not reported.	Yes
CPU, System	Advisory CPU_Sys_01 — The SysTick calibration value (register field CPU_SCS.STCR.TENMS) used to set up 10-ms periodic ticks is incorrect when the system CPU is running off divided down 48MHz clock.	Yes
CPU	Advisory CPU_04 — The Instrumentation Trace Macrocell (ITM) and Data Watchpoint and Trace (DWT) are active only if an external debug probe is attached to the JTAG port of the device.	Yes
System	Advisory Sys_01 — Device might boot into ROM serial bootloader when waking up from shutdown	Yes
System Controller	Advisory SYSCTRL_01 — Resets occurring in a specific 2MHz period during initial power up are incorrectly reported	Yes
IO Controller	Advisory IOC_01 — Limited number of DIOs available for the bootloader backdoor	Yes
ADC	Advisory ADC_02 — ADC samples can be delayed by two or 14 clock cycles (24MHz) when XOSC_HF is turned on or off, resulting in sample jitter.	Yes
Flash	Advisory Flash_02 — Flash bank erase may timeout when operating at low temperatures with a low VDD5 supply voltage.	Yes

2 Nomenclature, Package Symbolization, and Revision Identification

2.1 Device and Development Support-Tool Nomenclature

To designate the stages in the product development cycle, Texas Instruments™ assigns prefixes to the part numbers of all devices and support tools. Each device has one of three prefixes: X, P, or null (for example, XCC2674P10). Texas Instruments recommends two of three possible prefix designators for its support tools: TMDX and TMDS. These prefixes represent evolutionary stages of product development from engineering prototypes (X/TMDX) through fully qualified production devices/tools (null/TMDS).

Device development evolutionary flow:

- X** An experimental device that is not necessarily representative of the final device's electrical specifications and may not use production assembly flow.
- P** Prototype device that is not necessarily the final silicon die and may not necessarily meet final electrical specifications.
- null** The production version of the silicon die that is fully qualified.

Support tool development evolutionary flow:

- TMDX** Development-support product that has not yet completed Texas Instruments internal qualification testing.
- TMDS** Fully-qualified development-support product.

X and P devices and TMDX development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

Production devices and TMDS development-support tools have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (X or P) have a greater failure rate than the standard production devices. Texas Instruments recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

2.2 Devices Supported

This document supports the following device:

- [CC2674P10](#)

2.3 Package Symbolization and Revision Identification

Figure 2-1 and Table 2-1 describe package symbolization and the device revision code.




Figure 2-1. Package Symbolization

Table 2-1. Revision Identification

Device Revision Code	Silicon Revision
C	PG3.0

3 Advisories

Radio_01 *Proprietary radio modes: spurious emissions can affect regulatory compliance*

Revisions Affected: Revision C

Details: When the device's internal load capacitors are used with the external 48MHz crystal, energy couples from the crystal oscillator circuit to the RF output. This coupling causes spurious emissions at $N \times 48\text{MHz}$ from the carrier frequency. This includes, but is not limited to, the frequency bands supported by the device covered by the following regulations:

When using the +14dBm RF power amplifier

- ARIB T-108 (Japan)

When using the +20dBm RF power amplifier

- FCC CFR47 Part 15 (US)
- ETSI EN 300 220 (Europe)
- ETSI EN 300 328 (Europe)
- ETSI EN 300 440 (Europe)

Workaround: For compliance with affected standards, external load capacitors might be needed for the 48MHz crystal to reduce spurious emissions. Internal capacitors (default 7pF connected capacitance) must then be disconnected internally.

This workaround is implemented by defining the following symbols in the included customer configuration file (ccfg.c) available in the examples:

```
#define SET_CCFG_MODE_CONF_XOSC_CAPARRAY_DELTA -128
#define SET_CCFG_MODE_CONF_XOSC_CAP_MOD 0
```

Radio_02 *High-Power PA Operation at Temperatures Below -20°C May Affect the 32kHz Crystal Oscillator*

Revisions Affected: Revision C

Details: When using the high-power PA at temperatures below -20°C and high output power, the PA may affect the 32kHz crystal oscillator due to RF load impedance mismatch. In this situation, the crystal oscillator will stop, and provided the clock loss detector is enabled (OSC_DIG:CTL0.CLK_LOSS_EN = 1), the device will reset. Antenna impedances outside of VSWR of 2:1 must be avoided in all operating scenarios.

Workaround:

- For applications operating below -20°C, it is of particular importance to accurately follow the reference design for the RF balun and -matching network with respect to component values and layout. Amplitude- and phase balance through the balun must be <1dB and <6 degrees, respectively.
- For PCB designs not adhering to the TI recommended guidelines or in applications where antenna impedance is subject to change due to external factors, output power should be limited to 17dBm maximum.
- Make sure the clock loss detector is enabled, OSC_DIG:CTL0.CLK_LOSS_EN = 1, to properly reset the device should the crystal oscillator be stopped.

Radio_05 ***Zigbee has a negative 3dB RSSI offset error with internal bias***

Revisions Affected Revision C

Details Zigbee 2.4GHz PHY has an RSSI offset error of -3dB when internal bias is used. In consequence, this offset must be applied before the RSSI offset error of ± 4 dB specified in the data sheet is achieved.

Workaround The offset compensation is implemented in the SimpleLink F2 SDK version 7.10.02.23 and in SmartRF Studio version 2.30.

Power_03 ***Increased Voltage Ripple at Low Supply Voltages When DC/DC Converter is Enabled***

Revisions Affected: Revision C

Details: At supply voltages < 2.0 V, a hardware control module disables the DC/DC converter to maximize system efficiency. This module does not have enough hysteresis, causing approx 10mV of ripple on the VDDR-regulated power supply. Based on internal testing of the device, it is not anticipated that this erratum affects RF performance. However, these test results cannot ensure that a customer's application or end equipment will not be affected.

Workaround: Use the TI-provided Power driver (PowerCC26X2.c) which automatically disables the DC/DC converter when supply voltage is < 2.2 V.
The workaround is available in all SDK versions.

PKA_01 ***Public Key Accelerator (PKA) Interrupt Line is Always High When Module is Enabled and PKA is Idle***

Revisions Affected: Revision C

Details: When the PKA module is enabled and idle, the interrupt line is always high and the interrupt can thus not be used as is.

Workaround: The workaround is to disable the PKA interrupt in the interrupt service routine while the PKA module is idle and re-enable the interrupt right after starting an operation.
The workaround is implemented in the TI-provided cryptography drivers (ECDHCC26X2.c, ECDSACC26X2.c, ECJPAKECC26X2.c_list.c) available in all versions of the SimpleLink Software Development Kit (SDK) that support this device.

PKA_02 ***Public Key Accelerator (PKA) RAM is Not Byte Accessible***

Revisions Affected: Revision C

PKA_02 (continued) *Public Key Accelerator (PKA) RAM is Not Byte Accessible*

Details:

When accessing the PKA RAM, the RAM is not byte accessible. If a single byte is accessed (read or written), 4 bytes will be accessed instead.

Workaround:

The workaround is to use word access (4 bytes) when accessing the PKA RAM.

The workaround is implemented in the TI-provided cryptography drivers (ECDHCC26X2.c, ECDSACC26X2.c, ECJPAKECC26X2.c_list.c) available in all versions of the SimpleLink Software Development Kit (SDK) that support this device.

I2C_01*I²C Module Controller Status Bit is Set Late*

Revisions Affected:

Revision C

Details:

The I2C.MSTAT[0] bit is not set immediately after writing to the I2C.MCTRL register. This can lead an I²C controller to believe it is no longer busy and continuing to write data.

Workaround:

Add four NOPs between writing to the MCTRL register and polling the MSTAT register.

The workaround is implemented in the TI-provided I2C Controller driver (I2CCC26XX.c) and in the I2C driver Library APIs (driverlib/i2c.c).

The workaround is available in all Software Development Kit (SDK) versions.

I2S_01*I²S Bus Faults are Not Reported*

Revisions Affected:

Revision C

Details:

The I²S module will not set the bus error interrupt flag (I2S0.IRQFLAGS.BUS_ERR) if an I²S read or write causes a system bus fault that results from access to illegal addresses (usage error).

Workaround:

Software must ensure that memory area used by the I²S DMA is accessible, meaning that the memory is powered on and the system bus is connected.

As an example; The TI-provided SPI driver SPICC26X2DMA.c will ensure that the flash memory is kept accessible also in Idle power mode if the transmit buffer address starts with 0x0 to ensure no bus faults occur. A similar approach needs to be taken if writing a peripheral driver utilizing I2S.

CPU_Sys_01 ***The SysTick Calibration Value (Register Field CPU_SCS.STCR.TENMS) Used to Set Up 10 ms Periodic Ticks is Incorrect When the System CPU is Running Off Divided Down 48MHz Clock.***

Revisions Affected: Revision C

Details: When using the Arm® Cortex® SysTick timer, the TENMS register field (CPU_SCS.STCR.TENMS) will always show the value corresponding to a 48MHz CPU clock, regardless of the CPU division factor.

Workarounds: One of the following two workarounds must be implemented:

Workaround 1: Do not use a divided down system CPU clock. In general, power savings are maximized by completing a task at full clock speed and then stopping the system CPU entirely after the task is complete.

Workaround 2: Read the system CPU division factor from the PRCM.CPUCLKDIV.RATIO register and compensate the TENMS field in software based on this value.

TI-provided drivers do not offer any functionality to divide the system CPU clock.

CPU_04 ***The Instrumentation Trace Macrocell (ITM) and Data Watchpoint and Trace (DWT) are active only if an external debug probe is attached to the JTAG port of the device.***

Revisions affected: Revision C

Details: The debug subsystem power domain, which enables both the JTAG/cJTAG debugging and the trace capabilities of the device (ITM and DWT), remains powered off until a debug probe is attached to the JTAG port of the device. This prevents using any trace capabilities (data watchpoints, semihosting) in a standalone device.

Workaround: Power up the device with a debug probe attached, which also powers up the debug subsystem and maintains the functionality of ITM/DWT until a reset is issued.

Sys_01 ***Device Might Boot Into ROM Serial Bootloader When Waking Up From Shutdown***

Revisions Affected: Revision C

Details: For the conditions given below, the device will boot into and execute the ROM serial bootloader when waking up from Shutdown power mode. Intended behavior is to execute the application image. The prerequisites for this erratum to happen are:

- The wake up from Shutdown must be caused by toggling or noise on the JTAG TCK pin and not by a GPIO event.
- The Customer Configuration Section (CCFG) must have configured the bootloader with the following field values:

Sys_01 (continued) **Device Might Boot Into ROM Serial Bootloader When Waking Up From Shutdown**

- BOOTLOADER_ENABLE = 0xC5 (Bootloader enabled)
- BL_ENABLE = 0xC5 (Bootloader pin backdoor enabled)
- BL_PIN_NUMBER = n (any valid DIO number)

With the above prerequisites, the bootloader will be entered in the following cases:

- The CCFG bootloader pin level (BL_LEVEL) is set to 0x0 (active low) AND the input buffer enable for the DIO defined in BL_PIN_NUMBER is disabled in register IOC.IOCFGn.IE. If the input buffer is not enabled, the DIO level will always read 0 and bootloader will be entered.
- The input buffer is controlled by IOC.IOCFGn.IE is enabled and the DIO input value is the same level as the CCFG bootloader pin level (BL_LEVEL) when entering Shutdown (GPIO input values are latched when entering Shutdown).

Please refer to the ICeMelter chapter in [CC13x4x10, CC26x4x10 SimpleLink™ Wireless MCU TRM](#) for details on how noise entering the JTAG TCK pin can wake up the device.

Workarounds:

One of the following workarounds must be implemented:

- If the input buffer is not enabled, use only the active high bootloader pin level (BL_LEVEL).
- If input buffer is enabled, ensure DIO input pin level is not the same as bootloader pin level (BL_LEVEL) when entering Shutdown.

SYSCTRL_01 **Resets Occurring in a Specific 2MHz Period During Initial Power Up are Incorrectly Reported**

Revisions Affected: Revision C

Details:

If a reset occurs in a specific 2MHz period during the initial power-up (boot), the reset source in AON_PMCTL.RESETCTL.RESET_SRC is reported as PWR_ON regardless of the reset source. This means there is a window of 0.5µs during boot where a reset can be incorrectly reported.

Workaround:

None

IOC_01 **Limited number of DIOs available for the bootloader backdoor**

Revisions Affected: Revision C

Details:

The highest possible DIO number that can be used for the bootloader backdoor is limited to the number of available GPIOs minus 1. The bootloader backdoor pin is configured through SET_CCFG_BL_CONFIG_BL_PIN_NUMBER in ccfg.c. That means that if the device has x GPIOs, the highest DIO number that can be selected for the bootloader backdoor is DIO_{x-1}, even if higher DIO numbers are available for the device.

Workarounds:

There are no workarounds for this issue.

ADC_02 ***ADC samples can be delayed by two or 14 clock cycles (24 MHz) when XOSC_HF is turned on or off, resulting in sample jitter.***

Revisions Affected: Revision C

Details: There is no dedicated clock source selection for the ADC clock. The clock is derived from either XOSC_HF or RCOSC_HF but defaults to an XOSC_HF-derived clock whenever this is turned on.

When the ADC clock source is switched from RCOSC_HF to XOSC_HF-derived clock, the clock will stop for 2 cycles (24MHz).

When the ADC clock source is switched from the XOSC_HF-derived clock to the RCOSC_HF-derived clock, the clock will stop for an additional 12 clock cycles, as the RCOSC_HF-derived clock is not ready when the switch is done.

SCLK_HF switches from RCOSC_HF to XOSC_HF at different times, compared to the ADC clock. This leads to a sample jitter.

Workaround 1: Use asynchronous sampling

- This will reduce the delay of 14 clock cycles down to two clock cycles.
- Using asynchronous sampling and an external trigger source (GPIO input pin) will eliminate the delay completely

To use the ADC in asynchronous mode from the Sensor Controller:

Call `adcEnableAsync()` to enable the ADC, instead of `adcEnableSync()`

Example:

```
adcEnableAsync(ADC_REF_FIXED, ADC_TRIGGER_AUX_TIMER0);
```

To use the ADC in asynchronous mode from the System CPU, by using the ADCBuf driver:

```
ADCBuf_Params params;
ADCBufCC26X2_ParamsExtension paramsExtension;

ADCBuf_Params_init(&params);
ADCBufCC26X2_ParamsExtension_init(&paramsExtension);

paramsExtension.samplingMode = ADCBufCC26X2_SAMPING_MODE_ASYNCRONOUS;
params.custom = &paramsExtension;
```

To use the ADC in asynchronous mode from the System CPU, by using DriverLib API:

Call `AUXADCEnableAsync()` to enable the ADC, instead of `AUXADCEnableSync()`

Example:

```
AUXADCEnableAsync(AUXADC_REF_FIXED, AUXADC_TRIGGER_GPT0A);
```

Please note the difference between the asynchronous and synchronous ADC modes:

- In asynchronous mode, the ADC trigger ends the sampling period (which started immediately after the previous conversion) and starts the conversion.
- In synchronous mode, the ADC trigger starts the sampling period (with configurable duration), followed by conversion

Workaround 2: Ensure that XOSC_HF is not turned on or off while the ADC is used.

Flash_02 *Flash bank erase may timeout when operating at low temperatures with a low VDDS supply voltage.*

Revisions Affected: Revision C

Details: A full flash bank (512kB) erase operation can timeout if executed near the following conditions:

- Temperature of -40°C AND
- VDDS of 1.8V

The amount of bits to be erased in bulk can exceed the flash pump current limit at those extremes.

Workarounds: Reduce the effective size of the flash bank erase by partially protecting portions of the flash bank before attempting a new bank erase.

4 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from June 29, 2023 to February 1, 2025 (from Revision B (June 2023) to Revision C (February 2025))

	Page
• Added Advisory Flash_02.....	2
• Added Advisory CPU_04.....	2
• Removed Advisory Sys_06.....	2
• Updated to Silicon Revision C (PG3.0) throughout this document.....	2

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on [ti.com](https://www.ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265

Copyright © 2025, Texas Instruments Incorporated