


ZZ1 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.  
 ZZ2 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.  
 ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

ZZ4 ■ Add F1 fuse into XF1 fuse holder



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.  
 ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: HSDC077	REV: A	SUN REV: Not In VersionControl
	TID #: N/A		
PLOT NAME = TopAssembly Drawing	GENERATED : 11/12/2019 9:17:04 PM		TEXAS INSTRUMENTS

