

BT1

BT2

Power Supply
0.7-3V

J1
GND

PS VBAT
J3

VIN
J4

L1

VOUT
TP1

R3

C1

C2

U1

R2

R1

J5

ON EN OFF

J6
VBAT_OUT

J7
GND

TEXAS
INSTRUMENTS
PMP9771A

