Cascaded LMX1204 Phase-Error Analysis



Russell Hoppenstein

Systems Engineering and Marketing

ABSTRACT

The LMX1204 device is a high-frequency clock distribution device. The device is designed for distributing a clock or local oscillator source to multiple transceiver channels. Each device supports four outputs. The devices can be cascaded when more channels are needed with negligible performance impact. The Cascaded LMX1204 Reference Design uses two layers of the LMX1204 device to facilitate 16 outputs. This report measures and analyzes the phase response between the outputs to illustrate typical phase error response with a realistic device and layout configuration.

Table of Contents

| 1 Introduction | |
|--|--------------|
| 1 Introduction | <u>_</u> |
| 3 Measurement Results | |
| 3.1 Input/Output Return Loss | 5 |
| 3.2 Group Delay | . |
| 3.3 Phase Error Within One LMX1204 Device | 6 |
| 3.4 Phase Error Across all LMX1204 Channels | |
| 4 Conclusion | 7 |
| 5 References | 7 |
| List of Figures | |
| Figure 1-1. Cascaded LMX1204 Reference Design | 2 |
| Figure 1-2. Cascaded LMX1204 Clocking AFE7950 RF Sampling Transceivers in 64T64R Array | 3 |
| Figure 2-1. Cascaded LMX1204 Test Setup | 4 |
| Figure 3-1. Input/Output Return Loss | 5 |
| Figure 3-2. Group Delay Response | 5 |
| Figure 3-3. Phase Error Across Channels of one LMX1204 Device | 6 |
| Figure 3-4. Relative Phase Error Across Channels Over Multiple LMX1204 Devices | 6 |

Trademarks

All trademarks are the property of their respective owners.

Introduction Www.ti.com

1 Introduction

The LMX1204 is a high-frequency clock distribution device that supports up to 12.8 GHz. The device supports four outputs (each with a SYSREF output) and an additional low-frequency output designed for clocking an FPGA. The LMX1204 is designed for distributing a high-frequency clock to multiple RF sampling devices used in phased-array systems. In cases where more outputs are needed, the LMX1204 devices can be cascaded to multiply the number of outputs with negligible impact to clock quality. For the large phased-array systems, maintaining tight timing between the outputs is critical to make sure received signals line up properly.

The LMX1204 Reference Design cascades two layers of the LMX1204 device to distribute a clock to 16 outputs. Figure 1-1 shows a block diagram of the reference design. The cascaded approach is designed for clocking an array of AFE7950 RF sampling transceivers that support a 64T64R array system as depicted in Figure 1-2.

This note outlines measurements on an LMX1204 Reference Design designed to analyze the phase-error response in a typical configuration. This document is not intended to be a full characterization of the LMX1204 device itself as this reference design includes interconnecting traces and a bank of 0.5-m RF cables on the output. Use this application note as a general guideline for typical performance variation in a realistic configuration.




Figure 1-1. Cascaded LMX1204 Reference Design

www.ti.com Introduction




Figure 1-2. Cascaded LMX1204 Clocking AFE7950 RF Sampling Transceivers in 64T64R Array

Test Setup www.ti.com

2 Test Setup

The test setup uses a Network Analyzer to accurately measure the phase response through the distribution channels. Each port is calibrated to eliminate the contribution of the input source cable. The frequency range is set to 4 GHz to 8 GHz. The maximum frequency was limited by the upper frequency limit of the network analyzer. Figure 2-1 illustrates the test setup.




Figure 2-1. Cascaded LMX1204 Test Setup

www.ti.com Measurement Results

3 Measurement Results

3.1 Input/Output Return Loss

Figure 3-1 shows the input and output return loss of the cascaded LMX1204 reference design. Both responses show return loss performance less than -10 dB indicating a good $50-\Omega$ match and transmission lines on the board.




Figure 3-1. Input/Output Return Loss

3.2 Group Delay

Figure 3-2 shows the group delay through the reference design. The group delay response is proportional to the slope of the phase response. Group delay is a convenient way to visualize deviation from linear phase. For this reference design, the group delay is around 3.7 ns ± 0.4 ns. The response between device outputs is very consistent.




Figure 3-2. Group Delay Response

STRUMENTS Measurement Results www.ti.com

3.3 Phase Error Within One LMX1204 Device

Figure 3-3 shows the phase error relative to the average phase within one LMX1204 device across the 4 channels. Within a single device, the phase response is very consistent across each of the channels. Based on information from the LMX1204 data sheet, the expected skew between channels in one device is less than 2 ps. In this case, there is variation within the device in addition to tolerance variations within the output traces and RF cables.




Figure 3-3. Phase Error Across Channels of one LMX1204 Device

3.4 Phase Error Across all LMX1204 Channels

Figure 3-4 shows the phase error relative to the overall average between all output channels of the lower level LMX1204 devices comprising a total of 16 channels. This variation includes output trace and cables as the previous case in addition to the root LMX1204 device variation and feed traces. The phase error in this situation is also very consistent across all channels with LMX0 device being a small outlier. This is likely due to trace routing on the board and having to transition between the top and bottom layer for that device.




Figure 3-4. Relative Phase Error Across Channels Over Multiple LMX1204 Devices

www.ti.com Conclusion

4 Conclusion

The cascaded LMX1204 reference design illustrates excellent phase balance for clock distribution paramount for clocking high-speed data converters or driving transceiver local oscillator (LO) inputs. Within a given LMX1204 device, the phase error is generally within ±5 degrees. Between multiple devices, the phase error is generally within ±15 degrees.

In some applications, it can be more convenient to think about the error or mismatch between channels in terms of timing error as opposed to phase. The phase error can be converted to a time skew parameter at a given frequency using Equation 1.

$$\tau_{\text{skew}} = \frac{\phi_{\text{err}}[\text{deg}]}{360 \times f} \tag{1}$$

As an example, at 8 GHz, a 10-degree phase error translates to a skew error of 3.4 ps.

5 References

1. Texas Instruments, LMX1204 Low-Noise, High-Frequency JESD Buffer/Multiplier/Divider data sheet

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2023, Texas Instruments Incorporated