



Vishnu Balaraj

## ABSTRACT

The MCF8316A provides a single-chip, code-free sensorless FOC solution for customers driving BLDC motors for applications such as residential fans, ceiling fans, air purifiers, washer pumps, and so forth. With more than 50 parameters to tune, it can feel overwhelming and time consuming for customers to tune their motor and meet all system requirements. This application note provides an in-depth discussion of three of the most common design challenges with the MCF8316A and step-by-step guidance on how to address these challenges.

## Table of Contents

<b>1 Introduction</b> .....	2
<b>2 Design Challenges and Solutions</b> .....	2
2.1 Minimizing Motor Startup Time.....	2
2.2 Improving Motor Speed Stability – Tuning Speed PI Controller.....	8
2.3 Improving System Efficiency by Minimizing Power Losses.....	11
<b>3 References</b> .....	12

## List of Figures

Figure 2-1. Q-Axis Current and Motor Electrical Frequency During Align.....	3
Figure 2-2. Phase Current and FG During Align.....	4
Figure 2-3. Time Taken to Enter Closed Loop in Align.....	4
Figure 2-4. IPD Current Pulses in Tri-State and Brake Mode.....	5
Figure 2-5. Overlapping IPD Current Pulses.....	6
Figure 2-6. IPD Current Pulses Showing Ideal IPD Clock Frequency.....	6
Figure 2-7. Phase Current and FG During IPD.....	7
Figure 2-8. Time Taken to Enter Closed Loop in IPD.....	7
Figure 2-9. Q-Axis Current and Motor Electrical Frequency During Slow First cycle.....	8
Figure 2-10. Time Taken to Enter Closed Loop in Slow First Cycle.....	8
Figure 2-11. FG, Phase Current and Motor Electrical Speed in Hz With Auto Tuned Kp and Ki.....	9
Figure 2-12. FG, Phase Current and Motor Electrical Speed in Hz With Manually Tuned Kp and Ki.....	10
Figure 2-13. FG, Phase Current and Motor Electrical Speed in Hz When the Phase Current Drops From 3A to 1.5A.....	10
Figure 2-14. Thermal Image of MCF8316A – Higher Case Temperature.....	11
Figure 2-15. Thermal Image of MCF8316A - Lower Case Temperature.....	11

## Trademarks

All trademarks are the property of their respective owners.

## 1 Introduction

Some of the common challenges in tuning a Sensorless Field Oriented Control-based Motor driver are minimizing motor startup time, improving motor speed stability, and system efficiency. Motor startup time is very critical in applications such as Medical CPAP blowers. With the MCF8316A, system designers can minimize the motor start-up time by configuring the motor start-up parameters. Motor speed stability is critical in applications such as washer and dishwasher pumps, residential fans, and so forth. The integrated speed control loop in the MCF8316A helps maintain a constant speed over varying load conditions. For integrated control motor drivers, temperature is often a critical design specification that cannot be violated. With the MCF8316A, system designers can minimize power losses by configuring PWM output frequency, slew rate and PWM modulation scheme.

## 2 Design Challenges and Solutions

### 2.1 Minimizing Motor Startup Time

In this application note, startup time is defined as the time taken for the motor to enter closed loop from a stationary position. The MCF8316A provides four different motor startup methods as listed below:

- Align
- Double align
- Initial Position detect (IPD)
- Slow first cycle

Double align is not discussed in this application note as this method takes the maximum time to start up the motor.


#### 2.1.1 Align

The MCF8316A aligns the motor by injecting a DC current through a particular phase pattern for a certain duration of time. Below are the dominant parameters that impact startup time during align and open loop operation.

- Align time [ALIGN\_TIME]
- Align or slow first cycle current limit [ALIGN\_OR\_SLOW\_CURRENT\_LIMIT]
- Starting frequency of first cycle [FIRST\_CYCLE\_FREQ\_SEL]
- Open loop acceleration coefficient A1 [OL\_ACC\_A1]
- Open loop acceleration coefficient A2 [OL\_ACC\_A2]
- Auto handoff from open to closed loop [AUTO\_HANDOFF\_EN]
- Minimum BEMF for auto handoff [AUTO\_HANDOFF\_MIN\_BEMF]

Figure 2-1 shows the Q-axis current  $i_{qref}$  and motor electrical frequency  $f_{ele}$  with respect to time. During align, the motor driver ramps up the phase current from zero to the configured ALIGN\_OR\_SLOW\_CURRENT\_LIMIT. Current ramps at the rate configured by ALIGN\_SLOW\_RAMP\_RATE for the duration configured by ALIGN\_TIME.

After the align time, the MCF8316A begins to accelerate the motor in open loop with the first cycle open loop frequency configured by FIRST\_CYCLE\_FREQ\_SEL and ramps up the motor speed to the handoff frequency  $f_{ele}$ .



**Figure 2-1. Q-Axis Current and Motor Electrical Frequency During Align**

To minimize the motor startup time during align operation, it is recommended to decrease the align time [ALIGN\_TIME] and increase the align or slow first cycle current limit [ALIGN\_OR\_SLOW\_CURRENT\_LIMIT] to a value closer to the rated current of the motor.

**Note**

Decreasing the align time to a very low value might not provide sufficient time for the rotor to settle down to a known position. Also, increasing the align or slow first cycle current limit to a very high value might cause the rotor to oscillate or vibrate due to excessive torque.

To minimize the motor startup time in open loop operation, it is recommended to increase the Starting frequency of first cycle [FIRST\_CYCLE\_FREQ\_SEL], open loop acceleration coefficient A1 [OL\_ACC\_A1] and A2 [OL\_ACC\_A2], enable auto handoff [AUTO\_HANDOFF\_EN] and set the minimum BEMF for auto handoff [AUTO\_HANDOFF\_MIN\_BEMF] to 0 mV.

**Note**

Setting very high acceleration coefficients A1 and A2 can cause the motor to lose synchronization and result in a motor startup failure.

Figure 2-2 shows the FG and phase current of a BLDC motor. FG is configured to output pulses in closed loop. This is to know exactly at what point the motor enters closed loop. Bottom half of the figure shows the phase current that is zoomed to show the align current. The align current should be a DC current without any oscillations. Figure 2-3 shows the time taken for the BLDC motor to enter closed loop which is 363 ms.




Figure 2-2. Phase Current and FG During Align




Figure 2-3. Time Taken to Enter Closed Loop in Align


### 2.1.2 Initial Position Detect (IPD)

Initial Position Detection (IPD) method determines the initial position of the motor using the spatial variation in the motor inductance. IPD operates by sequentially applying six different phase voltage patterns. When the current through a particular phase pattern reaches the programmed threshold, the MCF8316A stops driving the particular phase pattern and measures the time taken from the start of the voltage that was applied to that particular phase pattern to the time that the current through the phase pattern reached the current threshold. This time varies as a function of the inductance in the motor windings. The state with the shortest time represents the state with the minimum inductance. The minimum inductance is because of the alignment of the north pole of the motor with this particular driving state.

Below are the dominant parameters that impact startup time during IPD. Open loop parameters are discussed in [Section 2.1.1](#).

- IPD current threshold [IPD\_CURR\_THR]
- IPD release mode [IPD\_RLS\_MODE]
- IPD Clock frequency [IPD\_CLK\_FREQ]
- IPD repeating times [IPD\_REPEAT]

Figure 2-4 shows the IPD current pulses along with the above four parameters labeled in the plot.



**Figure 2-4. IPD Current Pulses in Tri-State and Brake Mode**

Follow the below steps to minimize the motor startup time during IPD operation.

1. Configure the IPD current threshold [IPD\_CURR\_THR] to a value closer to the rated current of the motor.

---

**Note**

If the motor vibrates or spins in reverse direction, it is recommended to decrease the IPD current threshold.

---

2. Configure IPD release mode [IPD\_RLS\_MODE] to Tri-state or Hi-Z as the phase current has a faster settle-down time.


---

**Note**


Setting the IPD release mode to Tri-state can result in a voltage increase on VM. The user must manage this with an appropriate selection of either a clamp circuit or by providing sufficient capacitance between VM and GND to absorb the energy.

---

3. Increase the IPD Clock frequency [IPD\_CLK\_FREQ] until there is no overlapping between consecutive IPD current pulses as shown in Figure 2-6. IPD current should settle down completely before starting of the next pulse. Figure 2-6 shows an example of IPD current pulses with ideal time difference between the pulses. Figure 2-5 shows an example of an unsettled IPD current pulse where the consecutive current pulses overlap.



**Figure 2-5. Overlapping IPD Current Pulses**



**Figure 2-6. IPD Current Pulses Showing Ideal IPD Clock Frequency**

**Note**

Motor with high inductance and high current thresholds require longer time for the current to settle down. For such motors, it is recommended to set a lower IPD frequency. Setting a lower IPD frequency makes IPD noise louder and increases the motor startup time.

4. Configure IPD repeating times [IPD\_REPEAT] to 1.

Figure 2-7 shows the FG and phase current of a BLDC motor. FG is configured to output pulses in closed loop. This is to know exactly at what point the motor enters closed loop. The bottom half of the figure shows the phase current that is zoomed to show the IPD current pulses. Figure 2-8 shows the time taken for the BLDC motor to enter closed loop which is 219 ms.




Figure 2-7. Phase Current and FG During IPD




Figure 2-8. Time Taken to Enter Closed Loop in IPD

### 2.1.3 Slow First Cycle


In slow first cycle start-up method, MCF8316A starts motor commutation at a frequency defined by SLOW\_FIRST\_CYCLE\_FREQ. The frequency configured is used only for first cycle, and then the motor commutation follows acceleration profile configured by open loop acceleration coefficients A1 and A2. The slow first cycle frequency has to be configured to be slow enough to allow motor to synchronize with the commutation sequence.

Below are the dominant parameters that impact startup time during slow first cycle. Open loop parameters are discussed in Section 2.1.1.

- Frequency of first cycle [SLOW\_FIRST\_CYC\_FREQ]
- Align or slow first cycle current limit [ALIGN\_OR\_SLOW\_CURRENT\_LIMIT]

Figure 2-9 shows the Q-axis current  $i_{qref}$  and motor electrical frequency  $f_{ele}$  with respect to time.

During Slow first cycle, MCF8316A begins to accelerate the motor in open loop with the first cycle open loop frequency configured by FIRST\_CYCLE\_FREQ\_SEL and ramps up the motor speed to the handoff frequency  $f_{ele}$ .




**Figure 2-9. Q-Axis Current and Motor Electrical Frequency During Slow First cycle**

To minimize the motor startup time during slow first cycle operation, it is recommended to increase the frequency of first cycle [SLOW\_FIRST\_CYC\_FREQ] and increase the align or slow first cycle current limit [ALIGN\_OR\_SLOW\_CURRENT\_LIMIT] to a value closer to the rated current of the motor.

**Note**

Setting the frequency of first cycle to a very high value might cause the motor to lose synchronization. It is recommended to start with a lower value and slowly increase the frequency to ensure the motor spins smoothly. Increasing the align or slow first cycle current limit to a very high value might cause the rotor to oscillate or vibrate due to excessive torque.

Figure 2-10 shows the FG and phase current of a BLDC motor. FG is configured to output pulses in closed loop. This is to know exactly at what point the motor enters closed loop. Time taken for the BLDC motor to enter closed loop is 120 ms.



**Figure 2-10. Time Taken to Enter Closed Loop in Slow First Cycle**

**2.2 Improving Motor Speed Stability – Tuning Speed PI Controller**

The integrated speed control loop in MCF8316A helps maintain a constant speed over varying operating conditions. The Kp and Ki coefficients of the Speed PI controller are configured through SPD\_LOOP\_KP and SPD\_LOOP\_KI. These coefficients are tuned either manually or automatically to achieve better speed stability and speed regulation.

### 2.2.1 Auto Tuning

MCF8316A auto tunes Kp and Ki coefficients after measuring the mechanical parameters such as friction coefficient, moment of inertia through MPET.

Follow the below steps to auto tune Kp and Ki coefficients:

1. Program SPD\_LOOP\_KP and SPD\_LOOP\_KI to zero.
2. Enable MPET Ke measurement by setting MPET\_KE to 1.
3. Run the MPET by setting MPET\_CMD to 1. Motor starts to spin.
4. After motor stops spinning, SPD\_LOOP\_KP and SPD\_LOOP\_KI gets updated to auto tuned Kp and Ki values.
5. Issue run command and track the motor speed.
6. If there is any overshoot during ramp up, check the closed loop current and set the open loop current same as closed loop current.

Figure 2-11 shows the FG, phase current and motor electrical speed in Hz with auto tuned Kp and Ki. Motor speed steadily ramps up to the target speed without any overshoots.




Figure 2-11. FG, Phase Current and Motor Electrical Speed in Hz With Auto Tuned Kp and Ki

### 2.2.2 Manual Tuning

Kp and Ki coefficients can also be tuned manually by following below steps:

1. Disable Speed loop by setting SPEED\_LOOP\_DIS to 1.
2. Disable closed loop by setting CLOSED\_LOOP\_DIS to 1.
3. Spin the motor in open loop by issuing non-zero speed command.
4. Allow the open loop current to settle down and then measure the peak open loop phase current. Check the sign of the phase current by reading the Estimated Iq (register address: 0x000004E6).
5. Enter 110% of measured peak phase current as the Iq reference in FORCE\_IQ\_REF\_SPEED\_LOOP\_DIS. To convert Iq reference to FORCE\_IQ\_REF\_SPEED\_LOOP\_DIS, see the [MCF8316A Sensorless Field Oriented Control \(FOC\) Integrated FET BLDC Driver Data Sheet](#).
6. Enable closed loop by setting CLOSED\_LOOP\_DIS to 0.
7. Adjust the FORCE\_IQ\_REF\_SPEED\_LOOP\_DIS such that the motor speed reaches the maximum speed.
8. Calculate Speed loop Kp [SPD\_LOOP\_KP] and Speed loop Ki [SPD\_LOOP\_KI] using equation 1 and 2.
9. Enable speed loop by setting SPEED\_LOOP\_DIS to 0.

$$\text{Speed loop } K_p = \frac{I_q \text{ reference at maximum speed}}{\text{Maximum Electrical Speed in Hz}}$$

$$\text{Speed loop } K_i = 0.1 \times \text{Speed loop } K_p$$

Figure 2-12 shows the FG, phase current and motor electrical speed in Hz with manually tuned Kp and Ki. Motor speed steadily ramps up to the target speed without any overshoots.




Figure 2-12. FG, Phase Current and Motor Electrical Speed in Hz With Manually Tuned Kp and Ki

Figure 2-13 shows FG, phase current and motor electrical speed in Hz when the phase current drops from 3A to 1.5A. With well-tuned speed controller Kp and Ki coefficients, speed slightly overshoots for less than a second and recovers back to the steady state speed.




Figure 2-13. FG, Phase Current and Motor Electrical Speed in Hz When the Phase Current Drops From 3A to 1.5A

### 2.3 Improving System Efficiency by Minimizing Power Losses

Power dissipation in MCF8316A can be from various sources such as  $R_{dsOn}$  of the MOSFETs, MOSFET switching losses, MOSFET slew rate, operating supply current dissipation, and so forth. MCF8316A provides configurable options to minimize power losses and maximize thermal efficiency.

Power losses in MCF8316A can be minimized by enabling buck regulator power sequencing [BUCK\_PS\_DIS], increasing the slew rate [SLEW\_RATE], decreasing the PWM output frequency [PWM\_FREQ\_OUT] and configuring the PWM modulation scheme to “Discontinuous space vector PWM modulation”.

Figure 2-14 shows the thermal image of MCF8316A at Continuous PWM modulation, slew rate at 50 V/ $\mu$ s, 50 kHz and buck regulator power sequencing disabled. With these configurations, device case temperature is 109.8°C on a four-layer, 1 oz copper thickness PCB.




Figure 2-14. Thermal Image of MCF8316A – Higher Case Temperature

Figure 2-15 shows the thermal image of MCF8316A at discontinuous PWM modulation, slew rate at 200 V/ $\mu$ s, 20 kHz and buck regulator power sequencing enabled. With these configurations, device case temperature dropped to 75.4°C on a four-layer, 1 oz copper thickness PCB.




Figure 2-15. Thermal Image of MCF8316A - Lower Case Temperature

### 3 References

- Texas Instruments, [MCF8316A Sensorless Field Oriented Control \(FOC\) Integrated FET BLDC Driver Data Sheet](#)
- Texas Instruments, [MCF8316A Tuning Guide](#)
- Texas Instruments, [How to Design a Thermally-Efficient Integrated BLDC Motor Drive PCB](#)
- Texas Instruments, [Thermal Calculator](#)

## IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on [ti.com](http://ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265  
Copyright © 2022, Texas Instruments Incorporated