




THIS DRAWING IS INTENDED TO HELP IN THE ASSEMBLY OF THE DESIGN.

1. REFER TO ODB++ FILE FOR SPECIFIC COMPONENT LOCATION INFORMATION.
2. FINISHED ASSEMBLY MUST BE RoHS COMPLIANT. LABEL OR MARK "Pb FREE" IN THIS AREA ON TOP SIDE.



UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ARE: FRACTIONS DECIMALS ANGLES +/- .XX +/- .01 +/- +/- .XXX +/- .005 +/-	CONTRACT NO.		TEXAS INSTRUMENTS INC.	
MATERIAL SEE NOTE 5	APPROVALS	DATE	ASSEMBLY DRAWING TSW14J56 EVM	
	DRAWN L. MATHEN	08-05-13		
FINISH SEE NOTES 7, 8, 9	ENGR J. KETOWIC DRAWING		SIZE CODE IDENT NO DRAWING NO.	
			B	
DO NOT SCALE DRAWING			SCALE NONE	SHEET 1 OF 1